

# DRYLOK® FAST PLUG® Hydraulic Cement

## MANUFACTURER

**UNITED GILSONITE LABORATORIES**

**MAILING:** P.O. Box 70, Scranton, Pennsylvania, 18501

**SHIPPING:** 1396 Jefferson Avenue, Dunmore, Pennsylvania, 18509

**TOLL FREE:** 1-800-UGL-LABS (845-5227)

**PHONE:** 1-570-344-1202 • **FAX:** 1-570-969-7634

**www.ugl.com**



## PRODUCT DESCRIPTION

DRYLOK Fast Plug is a quick setting hydraulic cement. It sets in 3-5 minutes to stop active leaks, even under pressure. Seals open joints, very large cracks in masonry walls and floor and wall joints.

- Fast setting hydraulic cement
- Sets in 3-5 minutes
- Stops water, even under pressure
- Patch mortar joints, cracks and holes in masonry walls
- No top-coat required

## BASIC USES

Anchors metal to concrete. Ideal for sealing floor and wall joints and settlement cracks in masonry walls and swimming pools. This fast-setting hydraulic cement patches holes even where water is actively flowing through them.

## LIMITATIONS

Mix only enough for immediate use, because DRYLOK Fast Plug sets in 3-5 minutes. Cannot be reworked once it has set.

## TECHNICAL DATA

### COMPOSITION:

Sand and cement

### SHEN:

N/A

### % WEIGHT SOLIDS:

100%

### % VOLUME SOLIDS:

100%

### DENSITY (LBS./US GAL.):

24.0 ± 0.3%

### VISCOSITY:

N/A

### COLORS:

- Gray – ready mixed formula

## SET TIME:

- 3-5 minutes

**Note:** Maximum cure and dry time will be prolonged when slightly humid and when damp, cool conditions prevail.

## CLEAN UP:

Soap and water

Dispose of contaminated absorbent, container and unused contents in accordance with local, state and federal regulations.

## COVERAGE (SQ. FT./US GAL.):

- 16 cu. in./lb.

**Note:** Actual coverage will vary depending upon application method, surface texture and porosity.

## RECOMMENDED FILM THICKNESS/COAT:

N/A

## FLASH POINT:

N/A

## SHELF LIFE:

Unlimited in tightly closed container

## FREEZE/THAW:

N/A

## CONTAINER SIZES:

One and a half pound (US), four pound (US), ten pound (US) and fifty pound (US) containers

## VOC

N/A


## TINTING

N/A

## SURFACE PREPARATION

Wear eye protection, rubber gloves and a dust mask. The area to be patched should be cleaned thoroughly by wire brushing, scraping or any other effective process.

Back chisel out the area to be patched to the shape of an inverted "V" (the point at the



surface). This allows the patch to expand and lock into the surface. Wet down the area prior to patching to help the DRYLOK Fast Plug cure properly.

DRYLOK Fast Plug and clean mixing water should be at room temperature prior to mixing. Mix 3 parts Fast Plug and 1 part water thoroughly to a putty or heavy troweling consistency. This mixture will set in 3-5 minutes. The use of colder water will retard the setting time. Mix only enough for immediate use due to the quick setting time. DRYLOK Fast Plug cannot be reworked once it has set. In cold weather, use warm (90°F.) water for mixing; also soak surface with warm water before application.

## IMPORTANT

Mix only enough for immediate use, because DRYLOK Fast Plug sets in 3-5 minutes. Cannot be reworked once it has set.

Mix in small batches only. Mix only enough for use in 3 minutes. Discard all left over mixed patching material prior to starting a new batch. Left over patching material will chemically react with new material in the mixing receptacle.

## WARNING

If you scrape, sand, or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN.



**SET TIME:**

3-5 Minutes



Soap

**CLEAN-UP:**

Soap and Water



**COVERAGE:**

1 Application



**SPREAD RATE:**

16 Cu. In./Pound

PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH-approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to [www.epa.gov/lead](http://www.epa.gov/lead).

## APPLICATION

**For Active Leaks (the presence of flowing water through a break in the surface):** Mix appropriate amount of Fast Plug. In approximately 2½ - 3 minutes, the mixture will become warm to the touch which indicates it is commencing to set. At this time force the Fast Plug into the opening with the palm of the hand. Hold in place for 3-5 minutes, assuring a complete set and sufficient bond to stop the flow of water. The patched area may be smoothed and trimmed to the surrounding area in approximately 5 minutes. Fast Plug may be painted when set with DRYLOK Masonry Waterproofer, Latex Base DRYLOK Masonry Waterproofer, DRYLOK Powdered Masonry Waterproofer or DRYLOK Concrete Floor Paint.

**For Inactive Leaks, Patching, Anchoring:** Thoroughly soak the area to be patched. This will prevent the surface from sucking the water out of the patching material. Apply with knife or trowel. Use the surface to smooth the patch evenly. When anchoring, chisel or drill hole in the masonry surface slightly larger than item to be anchored. Make certain mixed Fast Plug is tamped firmly into hole and around metal part.

## CAUTION

Cancer hazard: Contains Crystalline Silica, which can cause cancer. Risk of cancer depends on duration and level of exposure to dust generated from sanding surfaces or grinding.

**Use only with adequate ventilation.** Do not breathe dust. Avoid eye contact or prolonged contact with skin. Avoid exposure to dust by wearing an appropriate (NIOSH

approved) particulate respirator during mixing, application and clean up. Follow respirator manufacturer's directions for respirator use. Close container after each use. Avoid contact with eyes, skin and clothing. Wash thoroughly after handling.

**First Aid:** If you experience difficulty in breathing, leave the area to obtain fresh air. If continued difficulty is experienced, get medical attention immediately. In case of eye contact, flush with plenty of water for at least 15 minutes. Consult a physician immediately.

## KEEP OUT OF REACH OF CHILDREN

This product contains a chemical known to the State of California to cause cancer.

## FIRST AID

**EYES:** Immediately flush eye thoroughly with water, continue flushing eye for at least 15 minutes, including under lids, to remove all particles. Call a physician.

**SKIN:** Wash skin with cool water and pH – neutral soap or mild detergent. See a physician if irritation is present.

**INGESTION:** Do not induce vomiting. If conscious, drink plenty of water. Call a physician.

**INHALATION:** Remove to fresh air, restore breathing. If breathing is difficult, administer oxygen. If not breathing, give artificial respiration.

For additional health and safety information please refer to the "Materials Safety Data Sheet".

## WARRANTY

N/A.

## SPECIFICATION

Compressive strength of cured material at:

- 1 Hour 311 PSI
- 3 Hours 365 PSI
- 8 Hours 396 PSI
- 24 Hours 2650 PSI
- 7 Days 3050 PSI
- 28 Days 11975 PSI



### Fast Plug® – Gray

1½ LB.	6/Case	.....00919
4 LB.	4/Case	.....00917
10 LB.	2/Case	.....00924
50 LB.	1/Case	.....00930

**DISCLAIMER:** This information is furnished without warranty, representation, inducement or license of any kind, except that it is accurate to the best of UGL's knowledge, or obtained from sources believed by UGL to be accurate, and UGL does not assume any legal responsibility for use or reliance upon same. Before using any product, read the label.